



Release Notes

Release Notes Version: V1.40, 2022-11-24

HiPath 3000 Manager

Software Version: V10 R3.12.0

☐ Major Release ☐ Minor Release ☒ Fix Release ☐ Hotfix Release

Current release status can be verified via the Software Supply Server (SWS)

Deliverables

☒ Full Release ☐ Delta Release

Export Control Classification Data

AL: N

ECCN: 5D002TSU

© Copyright 2022, Unify Software and Solution GmbH & Co. KG All rights reserved.

This document provides general information about the release, generics, and other relevant notes for the corresponding product and its correction versions.

The information provided in this document contains merely general descriptions or characteristics of performance which in case of actual use do not always apply as described or which may change as a result of further development of the products. An obligation to provide the respective characteristics shall only exist if expressly agreed in the terms of contract. Availability and technical specifications are subject to change without notice.

Atos, the Atos logo, Atos|Syntel are registered trademarks of the Atos group. © 2022 Atos.

Confidential information owned by Atos, to be used by the recipient only. This document, or any part of it, may not be reproduced, copied, circulated and/or distributed nor quoted without prior written approval from Atos.

Delivered Files

Product Item Number		File Name
1	P30152-P1532-P3-42	aek50781.exe Size: 52.281.344 Bytes
	HiPath 3000 Manager E	
2	P30152-P1532-T3-42	tkk50781.exe Size: 70.668.288 Bytes
	KC-Manager	

Table of Contents

1	HISTORY OF CHANGE	4
1.1	RELEASE NOTES CONTENT.....	4
1.2	PRODUCT VERSIONS HISTORY	4
2	CHANGES	5
2.1	IMPLEMENTED CHANGE REQUESTS / NEW FEATURES.....	5
2.2	RESOLVED REPORTED PROBLEMS / SYMPTOMS	5
2.3	RESOLVED VULNERABILITIES	5
3	IMPORTANT ISSUES, WORKAROUNDS, HINTS AND RESTRICTIONS	5
3.1	IMPORTANT ISSUES	5
3.2	WORKAROUNDS, HINTS	5
3.3	RESTRICTIONS	5
4	INSTALLATION AND UPGRADE / UPDATE	6
4.1	INSTALLATION	6
4.2	UPGRADE / UPDATE / MIGRATION	7
4.3	SPECIAL SETTINGS AND INSTRUCTIONS	7
5	HARDWARE AND SOFTWARE COMPATIBILITY	8
5.1	HARDWARE.....	8
5.2	FIRMWARE.....	8
5.3	LOADWARE.....	8
5.4	SOFTWARE / APPLICATIONS	8
5.5	OPERATING SYSTEMS	10
5.6	COMPLIANT PRODUCTS	11
6	SERVICE INFORMATION	12
6.1	MANAGEMENT INFORMATION BASE	12
6.2	LICENSE MANAGEMENT	12
6.3	REMOTE SERVICEABILITY	12
6.4	PRODUCT TOOLING STRUCTURE.....	12
6.5	CASE TRACKING SYSTEM.....	12
7	DOCUMENTATION REFERENCE.....	13
8	REFERENCES	13

1 History of Change

1.1 Release notes content

Version	Date	Description of changes
1.30	2020-10-02	Fix Release
1.31	2020-10-09	Fix Release
1.32	2020-11-23	Fix Release
1.33	2021-01-15	Fix Release
1.34	2021-03-10	Fix Release
1.35	2021-04-26	Fix Release
1.36	2021-06-10	Fix Release
1.37	2022-03-17	Fix Release
1.38	2022-04-11	Fix Release
1.39	2022-08-30	Fix Release
1.40	2022-11-24	Fix Release

1.2 Product versions history

Software Version	Production Version	Date	Remarks
V10 R3.2.0	P30152-P1532-P3-31 HA700B.50.610 P30152-P1532-T3-31	2020-10-02	Fix release
V10 R3.3.0	P30152-P1532-P3-32 HA700B.50.620 P30152-P1532-T3-32	2020-10-09	Fix release
V10 R3.4.0	P30152-P1532-P3-33 HA700B.50.630 P30152-P1532-T3-33	2020-11-23	Fix release
V10 R3.5.0	P30152-P1532-P3-34 HA700B.50.640 P30152-P1532-T3-34	2021-01-15	Fix release
V10 R3.6.0	P30152-P1532-P3-35 HA700B.50.710 P30152-P1532-T3-35	2021-03-10	Fix release
V10 R3.7.0	P30152-P1532-P3-36 HA700B.50.720 P30152-P1532-T3-36	2021-04-26	Fix release
V10 R3.8.0	P30152-P1532-P3-37 HA700B.50.730 P30152-P1532-T3-37	2021-06-10	Fix release
V10 R3.9.0	P30152-P1532-P3-38 HA700B.50.740 P30152-P1532-T3-38	2022-03-17	Fix release
V10 R3.10.0	P30152-P1532-P3-39 HA700B.50.750 P30152-P1532-T3-39	2022-04-11	Fix release
V10 R3.11.0	P30152-P1532-P3-41 HA700B.50.770 P30152-P1532-T3-41	2022-08-30	Fix release
V10 R3.12.0	P30152-P1532-P3-42 HA700B.50.781 P30152-P1532-T3-42	2022-11-24	Fix release

Note: List of all released software versions since [major] or [minor] software release in SWS

2 Changes

2.1 Implemented Change Requests / New features

Tracking Reference	Internal Reference	Summary
	OSBIZP-4156	ManagerE support for DIUT3

2.2 Resolved Reported Problems / Symptoms

Tracking Reference	Internal Reference	Summary
PRB000060613	OSBIZP-4159	Incorrect number of the overall configured PP's
PRB000059663	OSBIZP-4102	ManagerE crashes in specific menu when in windows is in Chinese
PRB000060257	OSBIZP-4175	Different display of the base stations between WBM and Manager E

2.3 Resolved Vulnerabilities

Not applicable for this release

3 Important Issues, Workarounds, Hints and Restrictions

This section provides the latest information at time of software release and is only pertaining to the time of release notes generation.

3.1 Important Issues

Not applicable for this release

3.2 Workarounds, Hints

Not applicable for this release

3.3 Restrictions

Manager C is not supported to administer an OSBiz V1 system

4 Installation and Upgrade / Update

4.1 Installation

4.1.1 Data and information security

It is mandatory to apply the Security Checklist so that system default settings are hardened according to best practices. This is most relevant after a first installation, but also strongly recommended after each Major or Minor version upgrade. It presents a checklist to ensure all necessary installation and configuration steps can be taken and adapted to the individual customer's environment and security policy. Deviations from the standard settings should be documented in the security checklist in consultation with the customer's contact person.

The best possible standard of data security and protection is only provided on our latest solutions or product versions. It is recommended to regularly install product updates in order to remove identified security vulnerabilities and software defects, improve stability and add latest functionality.

Country-specific regulations must be observed.

The latest version of "OpenScope Business V3 - Security Checklist" can be found under the following link: <https://nuxeo.unify.com/nuxeo/site/proxy/nxdoc/view/raw/b2efab60-4ba8-491c-988d-870077267c4a>

4.1.2 Safety improvements for Xpression Compact

Block outgoing traffic from Xpressions Compact (IVM) mailboxes by setting all IVM ports to system class-of-service (COS) 'outward-restricted' for day and night within HiPath 3000 Manager E.

Disable substitute feature for all mailboxes by deleting it from the IVM mailbox COS. For new installations IVM COS 3 shall be used as default instead of IVM COS 4.

Customers who need specific HiPath Xpressions Compact Features

The general rule above reliably blocks toll fraud but disables also the following features:

- o Call back external party from voice mailbox
- o Message notification call to external destination
- o Call forwarding to substitute number
- o Auto-attendant for external destinations
- o Xpressions Mobility (V3 only)
- o Xpressions Conference (V3 only)

In order a user to activate the above-mentioned features he has to set up a secure configuration in IVM.

In Auxiliary equipment - IVM - Additional Settings - Additional, the parameter "High-Security-Level IVM" is removed and the necessary security administration from now on will be possible through IVM's Web Based Management.

4.2 Upgrade / Update / Migration

4.2.1.1 Warning message for EVM and IVM ports

When a kds is retrieved or saved on an H3k/OSBiz system, the COS configuration is checked by Manager E. If an EVM/IVM is present and the ports belong to a COS group containing at least one trunk group that is not 'Outward restricted' a warning message will appear to improve security.

The warning message is also displayed when opening a H3k kds that is stored locally in the hard drive.

The error message cannot be deactivated unless the proposed configuration is applied.

4.2.2 Fallback

Not applicable for this release

4.3 Special settings and instructions

Not applicable for this release

5 Hardware and Software Compatibility

5.1 Hardware

Not applicable for this release

5.2 Firmware

Not applicable for this release

5.3 Loadware

Not applicable for this release

5.4 Software / Applications

Product	Software Version	Status	Nuxeo Note
HiPath 500 V5.0	P50038-P1054-A816-3 (V5.0 R0.0.0) M3 – Binder HE600S.03.580	GA	
HiPath 500 V6.0	P30152-P1205-P500-1 (V6.0 R7.0.0) M3 – Binder HE620S.07.536	GA	
HiPath 500 V7.0	P30152-P1266-P500-1 (V7 R3.4.0)	GA	
HiPath 500 V8.0	P30152-P1441-P500-2 (V8 R2.1.0)	GA	
HiPath 500 V9.0	P30152-P1536-P500-4 (V9R2.2.0)	GA	INF-12-000289
HiPath 2000 V1.0	P30152-P1194-P4-5 (V1.0 R3.3.0) M3 – Binder HE620Y.03.284	GA	
HiPath 2000 V2	P30152-P1337-P4-5 (V2 R1.0.1016) M3 – Binder HE641Y.00.0016	GA	
HiPath 3000 V4.0	P50038-P1010-A816-2 (V4.0 R2.0.0) P50038-P1011-A816-2 (V4.0 R2.0.0) M3 – Binder HE580*.03.266	GA	
HiPath 3000 V5	P50038-P1053-A816-3 (V5.0 R.0.0) P50038-P1054-A816-3 (V5.0 R.0.0) M3 – Binder HE600*.03.580	GA	
HiPath 3000 V6	P30152-P1205-P1-4 (V6.0 R5.0.0) P30152-P1205-P2-4 (V6.0 R5.0.0) M3 – Binder HE620*.05.373	GA	
HiPath 3000 V7	P30152-P1266-P1-9 (V7 R1.2.0) P30152-P1266-P2-9 (V7 R1.2.0) M3 – Binder HE641*.20.000	GA	
HiPath 3000 V8	P30152-P1441-P1 (V8 R5.6.0) P30152-P1441-P2 (V8 R5.6.0) and higher	GA	
HiPath 3000 V9	P30152-P1536-P1 (V9 R1.1.0) P30152-P1536-P2 (V9 R1.1.0) and higher	GA	INF-11-000649
HiPath 5000 CS V5.0	P30152-P1169-P3-1 (V5.0 R0.0.0) M3 – Binder HE620A.03.580	GA	
HiPath 5000 CS V6.0	P30152-P1205-P14-4 (V6.0 R0.0.0) M3 – Binder HE620A.05.373	GA	

Product	Software Version	Status	Nuxeo Note
HiPath 5000 CS V7	P30152-P1266-P14 (>= V7 R0.0.0)	GA	
HOOEE	P30152-P1337-Q8-2 (V1 R1.0.0) HE681Y.00.021 and higher	GA	
OpenScape Business V1	P30152-P1532-P1-13 or higher	GA	INF-13-000147
OpenScape Business V2	P30152-P1603-P1-04 or higher	GA	INF-15-000239
OpenScape Business V3	P30152-P1649-P1-28 P30152-P1649-P2-28 P30152-P1649-P3-28 or higher	GA	
Comfort Open V1.1, V1.0 Octopus F 270IT, Version 1.0	P30152-P1194-P4-5 (V1.0 R3.3.0) M3 – Binder HE620Y.03.284	GA	
Comfort Open V2	P30152-P1337-P4-5 (V2 R1.0.1016) M3 – Binder HE641Y.00.0016	GA	
Octopus F 200/400/600, Version 3.0 Octopus F 200/400/600, Version 4.0		GA	
Octopus F 200/400/600 V5.0 Octopus F 650 V5.0	P50038-P1053-T816-1 (V5.0 R0.0.0) P50038-P1054-T816-1 (V5.0 R0.0.0) M3 – Binder HE600*.03.580	GA	
Octopus F 200/400/600 V6.0 Octopus F 650 V6.0	P30152-P1205-T1-7 (V6.0 R7.0.0) P30152-P1205-T2-7 (V6.0 R7.0.0) M3 – Binder HE620*.07.537	GA	
Octopus F 100 V7 Octopus F 200/400 V7 Octopus F 650 V7	P30152-P1266-T1-70 (V7 R5.6.0) P30152-P1266-T1-9 (V7 R1.2.0) P30152-P1266-T2-9 (V7 R1.2.0) M3 – Binder HE641*.20.000	GA	
Octopus F 100 V8 Octopus F 200/400 V8 Octopus F 650 V8	P30152-P1441-T1 (V8 R5.6.0) P30152-P1441-T2 (V8 R5.6.0) or higher	GA	
Octopus F 100 V9 Octopus F 200/400 V9 Octopus F 650 V9	P30152-P1536-* (V9 R1.1.0) P30152-P1536-* (V9 R1.1.0) or higher	GA	
E730 V1.2 E930 V1.2 E20 Rel.3.1 E30 Rel.3.1 E10 Rel.3.0 E20 Rel.3.0 E30 Rel.3.0 E10 Rel.2.2 E20 Rel.2.2 E30 Rel.2.2		GA	
Octopus F X3/X5/X8	P30152-P1532-P1-13	GA	INF-13-000147

Product	Software Version	Status	Nuxeo Note
	P30152-P1532-P1-13 or higher		

5.5 Operating systems

Operating System Name	Operating System Version
Server	
Windows 2012 R2 - 2019 Server	All (32bit and 64 bit)
Clients	
Windows 8/8.1	All (Enterprise Edition is tested)
Windows 10	All (Enterprise Edition is tested)

5.6 Compliant products

This section lists the versions associated with the communication platforms, other products and third-party products that have been tested for use with this version of the product and are known to work.

5.6.1 Other products

Not applicable for this release

5.6.2 Third-Party products

Not applicable for this release

6 Service Information

6.1 Management information base

☐ Product sends SNMP V2 traps ☐ Product sends SNMP V3 traps ☐ Not supported

The following MIBs are supported:

6.2 License management

This product is licensed using:

☐ CLS ☐ CSC ☐ Other or not relevant, as described below

6.3 Remote serviceability

This product is certified for the following:

☐ RSP ☐ HiSPA ☐ RTPatch ☐ Other remote access or not relevant, as described below

6.4 Product tooling structure

Main Category	Management
Product Family	HiPath Meta Management
Product	HiPath 3000 Manager E
Product Version	HiPath 3000 Manager E V10
Product Item Number	P30152-P1532-P3-42

Main Category	OEM Products
Product Family	T-OCTOPUS F TOOL
Product	KC-MANAGER
Product Version	KC-MANAGER F200-F650, F270 IT
Product Item Number	P30152-P1532-T3-42

6.5 Case tracking system

Tickets can be generated and tracked via the Atos WEB Support Portal (AWSP).

<http://atosunify.service-now.com/unify>

A short instruction can be found on the AWSP directly.

7 Documentation Reference

The product documentation can be found on the Atos Unify Partner Portal <https://unify.com/en/partners/partner-portal> under Sell - Portfolio Information.

English	Documents	Hyperlinks	Remarks
	E-DOCU	Start E-Docu	
	Product E-Docu		
	Installation and Startup		
	Operating Manual		
	Quick Reference Guide		
	Administrator Manual		
	C-SWS	Start SWS Main Page	

8 References

Not applicable for this release